

T.5. 80 H.P. LE RHONE.




FIG. 13.

- |  |   |
|--|---|
| <p>A Screwed Plug.<br/>         B Casing.<br/>         C Wheel driven by large Wheel on Engine Thrust Box.<br/>         D Piston.<br/>         E Cylinder.<br/>         F Pivots on which Cylinder oscillates.<br/>         G Cylinder Port.</p> | <p>H Delivery Port.<br/>         I Inlet Port.<br/>         J Casing Cover.<br/>         K Oil Supply.<br/>         L Worm.<br/>         M Revolution Indicator Drive.<br/>         N Worm Wheel.<br/>         O Eccentric.</p> |
|--|---|